

TERRACE WALK ROAD SPACE RE-ARRANGEMENT  
FORMAL CONSULTATION

Name	Date	Comments	Opinion		Councils' response	Is it a relevant objections?
			For	Against		
	04/08/14	The proposal to change location of tour buses from south side of North Parade to the northern side (south side of Bog Island is welcomed, but concerned about the reduction in coach parking as a result of providing the loading bay for businesses in the south west corner of Terrace Walk.	✓		The tour bus location comment is noted. Whilst the effective reduction of coach parking space is acknowledged, there is also a requirement to provide balanced facilities for businesses within Terrace Walk.	N/A
	22/08/14	Lack of available coach parking space; unresolved transport strategy; better solution should be sought for coach drop-off and pick-up. high level of pollution; pedestrian safety concerns.		✓	Terrace Walk is seen as solution for drop-off and pick-up for now, but aims and recommendation from the emerging Transport Strategy is to identify a location with similar proximity and greater capacity. The data gathered from pollution monitoring concludes that although pollution levels can be high on occasions, they do not exceed the national levels. This is not to say that peak pollution levels have not caused a nuisance. Pedestrian safety concerns are acknowledged by the Council, although it is recognised that vehicles are travelling slowly through the area and the provision of safety stewards is also a useful aid.	Yes