

River Safety Report



Cathryn Humphries, Neighbourhood Environment Manager B&NES Council

Making Bath & North East Somerset an even better place to live, work & visit



Why did we commission the work from RoSPA?

- » Increased number of water related incidents on stretch of river between Churchill Bridge and Windsor Bridge
- » Many possible land ownership interests in this stretch of river with no clear lead organisation




Who did RoSPA consult with?

- » B&NES Council; Avon Fire and Rescue; Avon and Somerset Police
- » Universities
- » Environment Agency; British Waterways
- » Victim's families
- » Other stakeholders e.g. Sainsbury's



Main findings:



Making Bath & North East Somerset an even better place to live, work & visit



Main recommendations (short-term):

» Increase visibility of ladder 'cut outs'



Bath & North East Somerset Council

Main recommendations (short-term)

- » Vegetation management plan
- » Appropriate signage
- » Awareness raising campaign
- » Feedback to Bath Western Riverside development
- » Maintenance of 'grab lines'



Main recommendations (longer-term)

- » Repair fences of areas adjacent to towpath
- » Consider edge protection in high risk area
- » Arrange for debris to be removed from the river regularly



Next steps....

- » Agree action plan with partners
- » Continue to work with Universities to keep raising awareness

» Any questions?