

Effective: 01/09/2018 to 17/09/2020
Street: MEAD LANE (47903032)

Display Action Officer: No

Street: MEAD LANE (47903032)

Locality: SALTFORD, BATH AND NORTH EAST SOMERSET

Area: Saltford

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
No.:	1.00	Rd. - Locn.:	CW: From jnc. High Street to end	Asset Type:	Whole Street		Area:	Saltford
Batch:	30060331 - Inspection Batch			Route:	Area 4 - Keynsham		Date:	25/02/2019
30029437	PCLG - Urban - Light Traffic - 20mph - Approx 3m Working width - ch8 CARRIAGEWAY - 0.3x0.3m (FILLED WITH COLDLAY MATERIAL BY PCL ON 25/02/19)	25/02/2019	(SALTFORD) Level with back end of Jolly Sailor car park	Pothole	Internal		Committed	272765
Batch:	30058245 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	28/12/2018
30028443	Five potholes in the carriageway Done by AS Measurements and photographs	28/12/2018	Outside Sheldrake and Rockside	Pothole	Internal		Committed	271722
Batch:	30055900 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	25/10/2018
30027277	PCLG - Urban - Light Traffic - 20mph - Approx 3m working width - CH8 - CARRIAGEWAY - 3.5x1m	25/10/2018	(SALTFORD) Outside Cherry Cottage	Patching Defect	Internal		Committed	270359
Batch:	30055381 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	15/10/2018
30027028	PCLG - Urban - Light Traffic - 20mph - Approx 3m working width - CH8 - CARRIAGEWAY - 0.4x0.4m	15/10/2018	(SALTFORD) Outside Sheldrake	Pothole	Internal		Committed	270095
Batch:	3000370 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	31/05/2020
3000370	Closing road as to many people	31/05/2020		Emergency Callout	Internal		Archived	2750370
Batch:	2016825 - Inspection Batch			Route:	Area 4 - Keynsham		Date:	24/07/2020
	No actionable defects found							
Batch:	2012404 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	27/02/2020
2006324	PCL - (1) 0.5x0.5 (2) 1.5x0.5 (3) 4x1 (4) 1x0.4	27/02/2020	(SALTFORD) (1-3) Outside Cherry Cottage (4) Outside Marlyn LIASE WITH PC ON SITE	Carriageway Patching < 20 SQM	Internal		Archived	1005782
Batch:	2011976 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	19/02/2020
2006035	PCL - Place out x3 flood/road closed signs. Collect when flood has abated.	19/02/2020	(SALTFORD) At bridge & junction of Avon Lane	Road Sign	Internal		Archived	1005529
Batch:	2011966 - Inspection Batch			Route:	Area 4 - Keynsham		Date:	19/02/2020
	No actionable defects found							
Batch:	2010408 - Inspection Batch			Route:	Adhoc Inspection Route		Date:	13/01/2020
2005141	GULLY - clear gully, Suck out pot & jet through	13/01/2020	(SALTFORD) Under railway path arch	Jetting	Internal		Archived	1004713
Batch:	2005056 - Inspection Batch			Route:	Area 4 - Keynsham		Date:	16/08/2019
2002563	PCL - (1) 5x1 (2) 4x1 (3) 3x0.5 (4) 4.5x0.5 (5) 1x0.5 (6) 0.5x0.5	16/08/2019	(SALTFORD) (1-4) Opposite first mooring point (5) Outside Greenhills (6) Outside Jolly Sailor car park	Carriageway Patching < 20 SQM	Internal		Archived	1002368

Effective: 01/09/2018 to 17/09/2020
Street: MEAD LANE (47903032)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
No.:	1.00	Rd. - Locn.: CW: From jnc. High Street to end		Asset Type: Whole Street		Area: Saltford	
270095	PCLG - Urban - Light Traffic - 20mph - Approx 3m working width - CH8 - CARRIAGEWAY - 0.4x0.4m (Pothole)	(SALTFORD) Outside Sheldrake	P4 - 28 Calendar days	Contractor Completed	15/10/2018	24/10/2018	Act. HM03/225504
270359	PCLG - Urban - Light Traffic - 20mph - Approx 3m working width - CH8 - CARRIAGEWAY - 3.5x1m (Patching Defect)	(SALTFORD) Outside Cherry Cottage	P4 - 28 Calendar days	Contractor Completed	25/10/2018	13/12/2018	Act. HM03/225805
271722	PCL G)Five potholes in the carriageway Done by AS Measurements and photographs (Pothole)	Outside Sheldrake and Rockside	P1 - Emergency Works	Contractor Completed	28/12/2018	28/12/2018	Act. HM03/227043
272765	PCLG - Urban - Light Traffic - 20mph - Approx 3m Working width - ch8 CARRIAGEWAY - 0.3x0.3m (FILLED WITH COLDLAY MATERIAL BY PCL ON 25/02/19) (Pothole)	(SALTFORD) Level with back end of Jolly Sailor car park	P1 - Emergency Works	Contractor Completed	25/02/2019	25/02/2019	Act. HM03/227998